

## Sta. of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program

Supervisor XX

February 2, 2006

Mine Name: Brown's Canyon Operator Name: Mountain Valley Stone	Permit number: M/043/021 Inspection Date: May 26, 2005 Time: 10:30 am		
Inspector(s): Lynn Kunzler, DOGM Other Participants: Mark Willis Mine Status: Active			
Elements of Inspection	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads,</li> <li>Soils</li> <li>Revegetation</li> <li>Other</li> </ol>			
Purpose of Inspection: This inspection was done to document site conditions while in the area.			
Inspection Summary:  1 & 10. This permit received final approval on August 16, 2000. The Division has reviewed the site and permit for the purpose of escalating the reclamation surety for the next 5 years. The surety amount increased from \$25,000 to \$57,900. One major factor in this increase is the partial transfer of nearly 7 acres from the adjacent Park City Stone Mill to BMW. This transfer is ready for approval as soon as the Division receives the new surety. The operator is working with his insurance to obtain a surety bond for this amount. Hopes to have it finalized shortly.			
The quarry has progressed to the south. The hill that once stood between the quarry and the mill site is now removed. The waste pile has grown, but is still within the permitted area. The operator has plans to bring a contractor with a portable crusher to crush and screen some of the waste rock. The contractor has an air quality approval order for his crusher. This will reduce the volume of materials that will require regrading.			
Conclusions and Recommendations:  The site is in compliance at this time. It is recommended that the site be monitored when in the area.			
Photos were taken to document site conditions.			
Inspector's Signature  LK:pb  O:\M043-Summit\M0430021-BrownsCynRock-BMW\inspections\Ins		Date: <u>Februa</u>	ry 2, 2006
O. WIO+3-Summit/WIO430021-DIOWIISCYTROCK-DIVIW (Inspections/ins	p- 03202003.doc		